

Komatsu PC138US-11 (DEMO-EX01)

Plant ID: DEMO-EX01

Machine records, generated 07/10/2026, 22:57. A point-in-time copy: scan the QR code on the machine for the live record.

Status

In use today (as of 07/10/2026, 22:57)

Service due soon.

No open defects.

Paperwork status

Plant or machine insurance	Expiring in 20 days
Company-wide	
Public liability insurance (certificate of currency)	In date to June 2027
Plant / fleet insurance (covers all machines)	In date to June 2027
Workers compensation insurance (WorkSafe)	In date to September 2027

Service history

Date	What was done
01/10/2026	Grease all points
17/09/2026	Grease all points
17/09/2026	Hydraulic filter
06/09/2026	Engine oil and filter
03/09/2026	Grease all points
20/08/2026	Grease all points
06/08/2026	Grease all points
04/08/2026	Engine oil and filter
23/07/2026	Grease all points
09/07/2026	Grease all points

Recent prestarts

When	Operator	Reading	Result
07/10/2026, 06:29	Alex	2543.0	Pass
06/10/2026, 06:22	Sam	2536.0	Pass
05/10/2026, 06:15	Jordan	2528.0	Pass
04/10/2026, 06:36	Alex	2520.5	Pass
03/10/2026, 06:29	Sam	2513.5	Pass
02/10/2026, 06:22	Jordan	2505.5	Pass
01/10/2026, 06:15	Alex	2498.0	Pass
30/09/2026, 06:36	Sam	2491.0	Pass
29/09/2026, 06:29	Jordan	2483.0	Pass
28/09/2026, 06:22	Alex	2475.5	Pass

Risk assessment and SWMS

Document	Details
Risk assessment	Risk assessment, Komatsu PC138US-11 (demo) (version 1). Signed off 2026-09-27. Review by 2027-09-27. https://demo.deadsetsafety.com.au/m/ueErI2dAXXVrF02zdkCqQWzrdikyYh_ih2t5c_GAAWI/safety/1.pdf
SWMS	SWMS, Demo Site, Geelong (demo) (version 1). Signed off 2026-09-27. Review by 2027-09-27. https://demo.deadsetsafety.com.au/m/ueErI2dAXXVrF02zdkCqQWzrdikyYh_ih2t5c_GAAWI/safety/3.pdf